Dam Observer: Brandon Parret

Observation Date: 10/1/2022

Granite County, Flint Creek Dam

Owner's Observation Report

Weather: Rain shw..

Temperature: 46°

	Yes	No	Comments
Downstream Slope			
Signs of wet areas or seepage?		✓	none
Signs of slides or depressions?		✓	
Downstream Toe			
Signs of erosion?		✓	
Signs of seepage?		✓	
Embankment Crest			
Signs of settlement in roadway?		✓	
Instrumentation			
Reservoir elevation read?			Reading = 6427.93. Ice Cover? none
Piezometers read?			P1 Reading = none P2 Reading = none
Drain read?			P2 Reading = none
Outlet Works			
30" Hydropower release adjust		✓	Flow = _____ cfs
30" Stream bypass release adjust		✓	Flow = _____ cfs
30" Hydropower gate OK?	✓		
30" Stream bypass gate OK?	✓		
24" Gate OK?	✓		
Outlet pipes OK?	✓		
Stilling basin OK?	✓		
Signs of seepage?		✓	
Intake structure OK?	✓		
Public Safety			
Reservoir buoys and signs up?	✓		
Stilling basin signs up?	✓		
Spillway			
Debris at entrance?		✓	
Concrete and joints OK?	✓		
Stilling basin OK?	✓		
Supporting Information and Additional Comments			

nothing new to report